

| Station | Location | Approx. Cut/Fill*, ft | Boring Depth, ft | Ground water table, ft | Lab No. | In-place moisture | GDOT | Field Soil Description and Comments |
|-----------------|----------|-----------------------|------------------|------------------------|---------|-------------------|-------------|--|
| Ramp A 16+00 | 10' Rt | On Grade | BT @ 5' | NE | 4694 | 13.3% | IIB1 | 1.0' to 5.0' Dark grey sand |
| Ramp A 20+00 | 10' Rt | 4.0' Fill | BT @ 5' | 4.5 | 4695 | 11.8% | IIB2 | 0.0' to 2.0' Grey clayey sand 2.0' to 5.0' Hard, grey sandy clay, wet |
| Ramp A 25+00 | BL | 4.0' Fill | BT @ 5' | NE | 4696 | 14.7% | IIB1 | 1.0' to 5.0' Tan sand |
| Ramp A 30+00 | BL | On Grade | BT @ 5' | NE | 4697 | 10.3% | IIB1 | 1.0' to 5.0' Tan sand with some red clay |
| Ramp A 35+00 | BL | 15.0' Fill | | 1 | | | | No sample was taken, too wet, high ground water table |
| Ramp A 39+00 | 20' Rt | 22.0' Fill | | 0.5 | | | | No sample was taken, too wet, high ground water table |
| Ramp B 43+50 | BL | 13.0' Fill | BT @ 5' | NE | 4700 | 8.9% | IIB2 | 1.0' to 3.0' Grey sand/clay mix 3.0' to 5.0' Tan/grey sandy clay |
| Ramp B 48+00 | BL | 5.0' Cut | BT @ 4.5' | NE | 4701 | 6.8% | IIB2 | 1.0' to 2.5' Grey silty sand 2.5' to 4.5' Grey sand Hand auger refused at 4.5 feet |

* Depths of Fill/cut at boring locations are estimated from roadway cross sections

BT - Boring Terminated
NE - Not Encountered
AR - Auger Refusal