



PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2019-SAV-0099
Tag #: 4126
JobName: Peterson Road Lift Station

Date: 8/19/2019

Page 1 of 5

Customer Information

Company Name: LOWNDES COUNTY UTILITES DEPT
Address PO BOX 1349

VALDOSTA GA31603

Contact: Tim Devaine
Telephone:
Telephone:
Fax:
Email:

Following is an estimate prepared for you regarding the repair of your Flygt pump.

Product Identification

Product Number: 3300.091-6064

Serial Number: 3300.091-9760022

Model: 3300
Impeller Code: 466
HP: 88
Volts: 0
Phases: 3

Inspection Information

Inspected By:

Motor Data: Wire Configuration: U1:Red V1:Black W1:White
Megger to ground: R 0.00 B 0.00 W 0.00
Resistance through cable: RB 0.22 RW 0.23 BW
0.17
Stator Condition: Unusable
Shaft Condition: Fair
Oil Condition: Fair
Inspection Plugs:

Sensors:

- FLS
- CLS
- KLIX
- Bearing

Cable

Hydraulic: Impeller/Propeller Condition: Unusable
Volute Condition: Fair

Cable Condition: Unusable
Cable Length: 50'

