



PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2018-SAV-0162

Date: 11/18/2019

Page 1 of 5

Tag #: 3354

JobName: Francis Lake

Customer Information

Company Name: LOWNDES COUNTY UTILITES DEPT

Contact:

Address PO BOX 1349

Telephone:

Telephone:

VALDOSTA GA31603

Fax:

Email:

Following is an estimate prepared for you regarding the repair of your Flygt pump.

Product Identification

Product Number: 33000919672

Serial Number: 3300.091-9860003

Model: 3300

Impeller Code: 0642

HP: 75

Volts: 460

Phases: 3

Inspection Information

Inspected By: Bryan Atkins

Motor Data: Wire Configuration: U1:Red V1:White W1:Black

Megger to ground: R 550 B 550 W 550

Sensors:

Resistance through cable: RB n/a RW n/a BW

n/a

FLS

Stator Condition: Good

CLS

Shaft Condition: Unusable

KLIX

Oil Condition: Unusable

Bearing

Inspection Plugs:

Cable

Hydraulic: Impeller/Propeller Condition: Good

Cable Condition: Poor

Volute Condition: Poor

Cable Length:

